

# Table of contents

## Preface 11

- Prerequisites 11
  - Basic machining practice experience 11
  - Math 12
  - Motivation 12
- Controls covered 12
  - What about conversational controls? 13
  - Controls other than Fanuc 13
- Limitations 14
- Instruction method 14
  - Scope 14
  - Key Concepts approach 15
  - Lesson structure 15
  - Practice, practice, practice! 15
- Key Concepts and lessons 15

## Key Concept 1: Know your machine from a programmer's viewpoint 17

### *Lesson 1: Machine configurations 19*

- Vertical machining centers 19
  - C-frame style 19
    - Directions of motion (axes) for a C-frame style vertical machining center 20
    - Axis polarity 20
  - Knee style vertical CNC milling machines 21
  - Bridge-style vertical machining center (also called gantry-style) 22
- Horizontal machining centers 23
  - Directions of motion (axes) for a horizontal machining center 24
  - Axis polarity 24
- Programmable functions of machining centers 26
  - Spindle 26
    - Spindle speed 26
    - Spindle activation and direction 26
    - Spindle range 26
  - Feedrate 27
  - Coolant 28
  - Automatic tool changer 28
  - Measurement system mode (inch or metric) 29
- What else might be programmable? 30
- Key points for Lesson One: 30

### *Lesson 2: General flow of the CNC process 31*

- Companies that use CNC machining centers 31
  - What will you be doing? 32
- Flow of the CNC process 32
  - Study the workpiece drawing 32
  - Decision is made as to which CNC machine to use 32
  - The machining process is developed 33
  - Tooling is ordered and checked 33
  - The program is developed 33
  - Setup and production run documentation is made 33
  - Program is loaded into the CNC control's memory 33
  - The setup is made 33
  - The program is cautiously verified 34
  - Production is run 34
  - Corrected version of the program is stored for future use 34
- Key points for Lesson Two: 34

### *Lesson 3: Visualizing the execution of a CNC program 35*

- Program make-up 36
  - Method of program execution 36
  - An example of program execution 36
    - Manual milling machine procedure: 37
    - CNC program: 37
  - Sequence numbers 38
  - A note about decimal point programming 38
  - A decimal point tip 39
  - Other mistakes of omission 39
  - Modal words 39
  - Initialized words 39
  - Letter O or number zero? 39
  - Word order in a command 40
- Key points for Lesson Three: 40

### *Lesson 4: Program zero and the rectangular coordinate system 41*

- Graph analogy 41
  - What about the Z axis? 42
- Understanding polarity 43
- Wisely choosing the program zero point location 46
  - In X and Y 46
  - Reminder about axis movement 47

In Z 47	B 69
Absolute versus incremental positioning modes 49	C 69
A decimal point reminder 50	R 69
Key points for Lesson Four: 50	I, J, K 69
<i>Lesson 5: Determining program zero assignment values 51</i>	Q 70
Program zero assignment values 51	P 70
What is zero return position? 52	L 70
Determining program zero assignment values 53	F 70
How to manually measure the program zero point location on the machine 53	S 70
In X and Y for a square or rectangular workpiece 53	T 70
In X and Y for a round workpiece 55	M 71
In Z 56	D 71
Measuring the program zero point location using a spindle probe 57	H 71
Again, do you have to measure the program zero point? 58	EOB (end of block character) 71
How program zero point selection can affect the setup person 58	/ (slash code) 71
Key points for Lesson Five: 59	G and M codes 72
<i>Lesson 6: Assigning program zero 61</i>	G codes 72
Understanding fixture offsets 61	G code limitation: 72
A full example of program zero assignment 62	Option G codes 72
The program 62	What does initialized mean? 72
The setup 63	What does modal mean? 72
What is the common fixture offset? 64	The most popular G codes 72
What if my machining center doesn't have fixture offsets? 64	Common M codes used on a CNC machining center 74
Advantages of assigning program zero with fixture offsets instead of G92 64	Key points for Lesson Seven: 75
Safety 64	Key points for Key Concept one 76
Ease of use 64	
Efficiency 64	<b>Key Concept 2: You must prepare to write programs 77</b>
Rerunning tools 64	Preparation and time 77
Assigning program zero in the program 65	Preparation and safety 78
Key points for Lesson Six: 65	Typical mistakes 79
<i>Lesson 7: Introduction to programming words 67</i>	Syntax mistakes 79
Words allowing a decimal point 67	Motion mistakes 79
O 68	Mistakes of omission 79
N 68	Process mistakes 79
G 68	<i>Lesson 8: Preparation steps for programming 81</i>
X 68	81
Y 68	Prepare the machining process 81
Z 68	Develop the needed cutting conditions 83
A 68	An example 84
	Cutting conditions can be subjective 84
	Do the required math and mark-up the print 85
	Marking up the print 87
	Doing the math 88
	What about milling operations? 89
	Check the required tooling 90
	Plan the work holding set-up 91
	Other documentation needed for the job 92
	Production run documentation 93

Program listing 93	More on tolerances 120
Is it all worth it? 93	The initial setting for compensation 120
Key points for Lesson Eight: 93	When is trial machining required? 120
<b>Key Concept 3: Understand the motion types</b>	What happens as tools begin to wear? 121
<b>95</b>	What do you shoot for? 121
What is interpolation? 95	Why do programmers have to know this? 121
<i>Lesson 9: Programming the three most basic motion types 99</i>	Understanding offsets 121
Motion commonalties 99	Offset organization 122
Understanding the programmed point of each cutting tool 99	Offsets related to cutting tools 122
Center drill 100	Offsets related to program zero assignment 123
Spot drill 100	How offsets are instated 123
Drill 100	Key points for Lesson Ten: 124
Reamer 100	<i>Lesson 11: Tool length compensation 125</i>
Tap 100	The reasons why tool length compensation is needed 125
Boring bar 100	Programming tool length compensation 126
What about milling cutters? 101	Choosing the offset number to be used with each tool 126
G00 – Rapid motion (also called positioning) 102	An example program 127
How many axes can be included in a rapid motion command? 103	The setup person’s responsibilities with tool length compensation 128
About the dog-leg motion... 103	Recommended method: Using the tool’s length as the tool length compensation (offset) value 128
When do you use rapid motion? 104	Determining tool length compensation values 129
What is a safe approach distance? 104	Entering tool length compensation offsets 131
G01 – Linear interpolation (straight-line motion) 105	Using the distance from the tool tip to program zero as the tool length compensation (offset) value 132
Using G01 for a fast-feed approach 106	Determining tool length compensation values with this second method 132
A milling example 107	Reasons for using our recommended method 133
Drill holes with G01? 107	Typical mistakes with tool length compensation 133
G02 and G03 – Circular interpolation (circular motion) 108	Forgetting to instate tool length compensation 133
Which positions to program 108	Forgetting to enter the tool length compensation value 134
Specifying circular motion with the R word 108	Mismatching offsets 134
The R word is not modal 110	What if my machine doesn’t have fixture offsets? 134
More details about clockwise versus counter clockwise circular motion 110	Trial machining with tool length compensation 134
Circular motion with directional vectors (I, J, and K) 111	When trial machining is not required 135
Arc limitations 112	Sizing with tool length compensation 135
Full circle in one command 113	A tip for remembering which way to adjust the offset 135
Planning your own tool paths 115	
Key points for Lesson Nine: 115	
<b>Key Concept 4: Know the compensation types</b>	
<b>117</b>	
<i>Lesson 10: Introduction to compensation 119</i>	
What is compensation and why is it needed? 119	

<ul style="list-style-type: none"> <li>What if I use the second method shown for tool length compensation? 135</li> <li>Do I have to make all these calculations when adjusting offsets? 135</li> <li>Why can't I just change the Z coordinate/s in the program to make sizing adjustments? 136</li> <li>Key points for Lesson Eleven: 136</li> </ul>	<ul style="list-style-type: none"> <li>Is the milling cutter machining on both sides of the workpiece (are you measuring over two machined surfaces)? 159</li> <li>A tip for remembering which way to adjust the offset 160</li> <li>How important is it that you make your first workpiece a good one? 160</li> <li>When trial machining is not required 160</li> <li>Sizing with cutter radius compensation 160</li> <li>What if I use a CAM system and the offset value is the deviation from the planned cutter size? 161</li> <li>Do I have to make all these calculations when adjusting offsets? 161</li> <li>Why can't I just change programmed coordinate/s in the program to make sizing adjustments? 161</li> <li>Key points for Lesson Twelve: 161</li> </ul>
<p><b>Lesson 12: Cutter radius compensation 139</b></p> <ul style="list-style-type: none"> <li>Reasons why cutter radius compensation is required 139</li> <li>Calculations are simplified for manual programmers 139</li> <li>Range of cutter sizes 141 <ul style="list-style-type: none"> <li>Do you use re-sharpened (re-ground) cutters? 142</li> </ul> </li> <li>Trial machining and sizing 143</li> <li>Rough and finish milling with the same set of coordinates 143</li> <li>How cutter radius compensation works 144</li> <li>Steps to programming cutter radius compensation 145 <ul style="list-style-type: none"> <li>Step one: Instate cutter radius compensation 145 <ul style="list-style-type: none"> <li>The XY motion to the prior position 145</li> <li>The Z motion/s to the Z axis work surface 147</li> </ul> </li> <li>The command instating cutter radius compensation that positions the cutting tool to the first surface to mill 147 <ul style="list-style-type: none"> <li>G41 or G42? 147</li> <li>The offset used with cutter radius compensation 148</li> <li>The motion to the first work surface 149</li> </ul> </li> </ul> </li> <li>Step two: Program the tool path to be machined 150</li> <li>Step three: Cancel cutter radius compensation 152 <ul style="list-style-type: none"> <li>What if I have more than one contour to mill? 153</li> </ul> </li> <li>Examples 154 <ul style="list-style-type: none"> <li>What if I use a computer aided manufacturing (CAM) system to prepare programs? 156</li> <li>The setup person's responsibilities with cutter radius compensation 156</li> <li>Rough and finish milling with the same set of tool path coordinates 156 <ul style="list-style-type: none"> <li>A warning 158</li> </ul> </li> <li>Trial machining with cutter radius compensation 158</li> <li>159</li> </ul> </li> </ul>	<p><b>Lesson 13: Fixture offsets 165</b></p> <ul style="list-style-type: none"> <li>Assigning multiple program zero points 166 <ul style="list-style-type: none"> <li>Programming with multiple program zero points 168 <ul style="list-style-type: none"> <li>The potential trade-off with this method 169</li> <li>Reminder about tool length compensation values 169</li> </ul> </li> </ul> </li> <li>Shifting the point of reference for fixture offset entries 170</li> <li>Programming fixture offset entries 172</li> <li>Some other applications for the common fixture offset 173 <ul style="list-style-type: none"> <li>Allowing for variations in pallet changers 173</li> <li>Allowing for variations after a mishap 173</li> <li>Differences in spindle gap from one machine to another 173</li> <li>To enhance safety during dry-runs 173</li> </ul> </li> <li>Key points for Lesson Thirteen: 173</li> </ul> <p><b>Key Concept 5: You must provide structure to your CNC programs 175</b></p> <p><b>Lesson 14: Introduction to program structure 177</b></p> <ul style="list-style-type: none"> <li>Objectives of your chosen program structure 177</li> <li>Reasons for structuring programs with a strict and consistent format 177 <ul style="list-style-type: none"> <li>Familiarization 177</li> <li>Consistency 178</li> </ul> </li> </ul>

Re-running tools in the program 178	G84 – Right-hand tapping cycle 203
Efficiency limitations 179	G74 – Left-hand tapping cycle 205
Machine variations that affect program structure 179	G82 – Counter-boring cycle 205
M code differences 179	G89 – Counter-boring cycle for a boring bar 205
Automatic tool changer variations 180	G86 – Standard boring cycle (leaves drag line witness mark) 206
T word brings a tool to the ready station, M06 commands the tool change 180	G76 – Fine boring cycle (leaves no witness mark) 206
T word does everything 182	G85 – Reaming cycle (most programmers use G81 for reaming) 208
Tool change at beginning or end? 183	G87 and G88 – Manual cycles (not recommended) 208
Does the machine even have an automatic tool changer? 183	Words used in canned cycles 208
Understanding the G28 command 183	A simple example 208
What about G53? 184	Understanding G98 and G99 210
A possible problem with initialized modes 185	Canned cycles and the Z axis 212
How to use our given formats 185	Extended example showing canned cycle usage 214
Key points for Lesson Fourteen: 186	Using canned cycles in the incremental positioning mode 218
<i>Lesson 15: Four types of program format 187</i>	Key points for Lesson Sixteen: 220
Format for vertical machining centers 187	<i>Lesson 17: Working with subprograms 223</i>
Program Start-Up Format: 188	The difference between main- and subprograms 223
Tool Ending Format: 188	Loading multiple programs 225
Tool Start-Up Format: 188	Words used with subprograms 225
Program Ending Format: 188	Nesting subprograms 226
A note about documentation 190	Machining multiple identical pockets 226
Example program for vertical machining centers 191	Understanding G52 – temporary shift of program zero 228
More on the optional stop word (M01) 192	Multiple hole-machining operations on a series of holes 228
Where is the restart command for each tool? 192	Rough and finish contour milling 230
What if my machine doesn't have fixture offsets? 193	Two utility applications for subprograms 231
Format for horizontal machining centers 194	Control programs 231
Program Start-Up Format: 194	A trick to get more fixture offsets 232
Tool Ending Format: 195	What is parametric programming (custom macro B)? 234
Tool Start-Up Format: 195	Key points for Lesson Seventeen: 236
Program Ending Format: 195	<i>Lesson 18: Other special programming features 237</i>
Key points for Lesson Fifteen: 196	Block delete (also called optional block skip) 237
<b>Key Concept 6: Special features that help with programming 199</b>	Applications for block delete 238
<i>Lesson 16: Hole-machining canned cycles 201</i>	Another optional stop 238
Canned cycle commonalities 202	Trial machining 238
Description of each canned cycle 202	Sequence number (N word) techniques) 241
G80 – Cancel the canned cycle mode 202	Eliminating sequence numbers 241
G81 – Standard drilling cycle 202	
G73 – Chip-breaking peck drilling cycle 202	
G83 – Deep-hole drilling cycle (full retract between pecks) 202	

- Using special sequence numbers for each tool start up 241
- Using sequence numbers as statement labels 242
  - Using block delete to exit a series of commands 242
  - Using statement labels to change machining order 243
- Other G codes of interest 244
  - Thread milling, G02 & G03 244
  - G04 - Dwell command 246
  - G09 and G61 - Exact stop check 247
  - G10 - Offset setting by programmed command 248
    - Applications for G10 248
  - Polar coordinates (G15 and G16) 250
  - Plane selection commands (G17, G18, and G19) 251
  - Inch/metric mode selection G20, G21 252
  - Secondary reference position, G30 253
  - Scaling commands, G50 & G51 253
    - G50.1 and G51.1 - Mirror image commands 253
      - Applications for mirror image 253
      - The two ways to activate mirror image 254
  - Motion relative to zero return position, G53 255
  - Single direction positioning mode, G60 255
    - Coordinate rotation G68 and G69 256
- Key points for Lesson Eighteen: 258
- Lesson 19: Programming rotary devices 259*
  - The difference between an indexer and a rotary axis 259
  - A note to horizontal machining center programmers 259
  - Benefits of rotary devices 260
  - Indexers 260
    - Programming indexer rotation 260
      - 90 degree and 45 degree indexers 260
      - Five degree indexers 260
      - One degree indexer 261
  - Rotary axes 261
    - How to program a rotary axis departure 261
    - Comparison to other axes 262
      - Zero return position 262
      - Polarity 263
      - Designation of program zero 263
      - Absolute positioning mode 264
      - Incremental positioning mode 267
      - Rapid and straight line motion 269
    - Canned cycle usage 270
  - Approaching rotary device applications 270
    - Program zero point selection 270
      - Assigning one program zero point per side 272
      - Using one central program zero point 272
    - Example program using rotary device 274
    - Key points for Lesson Nineteen: 280
  - Key Concept 7: Know your machine from an operator's viewpoint 281**
    - The need for hands-on experience 282
      - More on axis polarity 283
    - Procedures you must know about 285
      - Machine power-up 285
      - Sending the machine to its zero return position 285
      - Manually moving each axis 285
        - An example of manual axis movement 286
      - Manually starting the spindle 286
      - Manually making tool changes 287
      - Manipulating the display screen 287
        - The position display screen 287
        - The program display screen 287
        - The offset display screen 288
        - The program check display screen 288
      - Loading programs 288
  - Lesson 20: Tasks related to setup and running production 289*
    - Setup-related tasks 292
      - Tear down the previous setup and put everything away 293
      - Gather the components needed to make the setup 293
      - Make the workholding setup 293
      - Assign the program zero point 294
        - Measure program zero assignment values 294
        - Enter program zero assignment values into fixture offset number one 296
      - Assemble the cutting tools needed for the job 296
      - Measure tool length- and cutter-radius-compensation values 297
        - The static nature of cutting tool measurements 298
      - Enter tool length and cutter radius compensation values into offsets 298

Load cutting tools into the machine's automatic tool changer magazine 299	Feed hold button 318
Load the CNC program 299	Feedrate override switch 319
Verify the correctness of a new or modified program 299	Rapid traverse override switch 319
Verify the correctness of the setup 301	Emergency stop button 319
Dry running our example program 301	Conditional switches 320
Cautiously run the first workpiece 302	Dry run on/off switch 320
The most dangerous time 303	Single block on/off switch 320
Making sure the first workpiece is a good one 304	Block delete on/off switch (also called optional block skip) 320
If necessary, optimize the program for better efficiency 306	Optional stop on/off switch 320
If changes have been made to the program, save the corrected version of the program 306	Buttons and switches for manual functions 320
Production-run-tasks 307	Axis jogging controls 321
Remove the previous workpiece 308	Handwheel controls 321
Load the next workpiece 308	Spindle control 321
Activate the cycle 308	Automatic tool changer control 321
Monitor the cycle 309	Indicator lights and meters 322
Clean and de-burr the workpiece 309	Spindle rpm and horsepower meters 322
Perform specified measurements 310	Axis drive-motor horsepower meter 322
Make offset adjustments to maintain size for critical dimensions 310	Cycle indicator lights 322
Replace worn tools 311	Zero return position indicator lights 322
Clean the machine 311	Optional stop indicator light 322
Preventive maintenance 311	Other buttons and switches on the machine panel 322
Key points for Lesson Twenty: 311	Other operation panels on your machining center 322
<i>Lesson 21: Buttons and switches on the operation panels 313</i>	<b>Key Concept 8: Know the three basic modes of operation 323</b>
The two most important operation panels 313	<i>Lesson 22: The three modes of operation 323</i>
The control panel buttons and switches 313	The manual mode 323
Display screen control keys (soft keys) 314	The manual data input mode 324
Position display pages 315	The manual data input (MDI) mode switch position 324
Program display pages 315	Commanding an MDI zero return 324
Offset display pages 315	The complete procedure to give an MDI command 325
Program check display pages 316	Commanding an MDI tool change 325
Other display screen modes 316	Commanding spindle activation with MDI 325
The keyboard 317	Other times when MDI is used 326
Letter Keys 317	Can you make motion commands with MDI? 326
The slash key (/) 317	The edit mode switch position 326
Number keys 317	To make a program in memory the active program (to call up a program) 327
Decimal point key 317	To enter a new program 327
The input key 317	The program operation mode 328
Cursor control keys 317	To run the active program from the beginning 328
Program Editing Keys 317	
Reset key 317	
The machine panel 318	
Mode switch 318	
Cycle start button 318	

**Key Concept 9: Understand the importance of procedures 329**

*Lesson 23: The key operation procedures 330*

**Key Concept 10: You must know how to safely verify programs 341**

Safety priorities 341

Operator safety 341

Machine tool safety 342

Workpiece safety 342

*Lesson 24: Program verification 343*

Two more procedures 343

Canceling the CNC cycle 343

To re-run a tool 344

Verifying a job that contains mistakes 346

Loading the program 349

The dry run to check for setup mistakes

350

Cautiously running the first workpiece

352

**INDEX 353**